




Передат.отношение	1:1
Скор.вращ. вход.	max. 6000 об/мин
Скор.вращ. выход	max. 6000 об/мин
Выходн. вращ. момент	max. 25 Нм
Направл. вращения	
Объем поставки	without wrench and collets

* Actual size inscribed on the tool

Комплект. Collets see Equipment for Toolholders Z2.1
Sealing washers see Equipment for Toolholders Z4.1
Wrench for spindle 10006
PRECI-FLEX® Adapter
Spindle cover see P99.1
Spindle sealing see P99.1
Coolant tubes 218.844.220



19.10.2004	11.04.2007
------------	------------